

# HUMS FACT SHEET

ATTENTION CUSTOMER BUSINESS MANAGERS,  
AUTHORIZED DISTRIBUTORS, & OPERATORS



STC No.: <b>SR02120NY-D</b>		<b>Agusta Bell AB139</b>																					
STC Holder: Honeywell International Inc 23500 W. 105th Street Olathe, KS 66061																							
STC Issue Date: 2006 SEPT																							
STC Reissue Date: 2009 JUN																							
Applicable to: AB139																							
HUMS Model: Model VXP																							
<b>NOTE:</b> Supports either Pratt & Whitney or Turbomeca engines																							
<b>SUMMARY:</b> <p>Honeywell has developed an automated vibration monitoring system for the Agusta Bell AB139 helicopter. The VXP Kit provides the AB139 helicopter a comprehensive rotor, engine and drive train system vibration monitoring capability.</p> <p>The system utilizes its vibration monitoring capability to make discretionary rotor and balance adjustments. No pilot interface is required during flight operations. The Rotor Track &amp; Balance (RT&amp;B) solution generated on-board and downloaded to the PC ground station for display to the maintenance personnel.</p> <p>The on-board system automatically acquires and processes sensor data, continuously monitors real-time condition and health indices, records aircraft intelligent information and saves data for post-flight analysis in the ground station.</p> <p>Software provided with the ground station assists maintenance personnel to perform aircraft maintenance and troubleshooting. For QA personnel, the software allows the review of the aircraft condition and health status, perform analysis, trending, and analysis to generate maintenance action (work order).</p> <p>Operators are utilizing the information from the VXP to enhance safety, reduce maintenance costs, and increase aircraft availability.</p>																							
<b>MAJOR COMPONENT PART NUMBERS:</b> <table><thead><tr><th>Part Number</th><th>Qty</th><th>Description</th></tr></thead><tbody><tr><td>915-17533</td><td>1</td><td>AB139 VXP Installation Kit</td></tr><tr><td>901-17546</td><td>1</td><td>Cockpit Control Unit</td></tr><tr><td>906-17784</td><td>1</td><td>Remote DU, Center Console Panel</td></tr><tr><td>901-11800-3</td><td>1</td><td>Optical Blade Tracker</td></tr><tr><td>906-17790</td><td>1</td><td>Tracker Bracket</td></tr><tr><td>901-17330</td><td>1</td><td>VXP Display Unit</td></tr></tbody></table>			Part Number	Qty	Description	915-17533	1	AB139 VXP Installation Kit	901-17546	1	Cockpit Control Unit	906-17784	1	Remote DU, Center Console Panel	901-11800-3	1	Optical Blade Tracker	906-17790	1	Tracker Bracket	901-17330	1	VXP Display Unit
Part Number	Qty	Description																					
915-17533	1	AB139 VXP Installation Kit																					
901-17546	1	Cockpit Control Unit																					
906-17784	1	Remote DU, Center Console Panel																					
901-11800-3	1	Optical Blade Tracker																					
906-17790	1	Tracker Bracket																					
901-17330	1	VXP Display Unit																					



# HUMS FACT SHEET

Attention Customer Business Managers, Authorized Distributors, & Operators

STC No.: **SR02120NY-D**

**Agusta Bell AB139**

## SENSORS:


15 Vibration sensors and 2 tachometer/photocell inputs

Tail rotor radial  
MGB input #1  
Cabin lateral  
Engine #2 turbine  
Eng #2 ACC GB

Tail rotor axial  
MGB input #2  
Cabin vertical  
MGB quill  
Tail rotor tachometer

Tail rotor IGB  
Hanger bearing  
Engine #1 turbine  
Eng #1 ACC GB  
Main rotor tachometer

## INSTALL LOCATIONS:



## OPTIONS:

For technical support and additional information, please contact:

Brian C. Hatcher  
Phone: (909) 930-3600 Ext. 222  
Cell: +1-949-690-2914  
[brian.hatcher@dsi-hums.com](mailto:brian.hatcher@dsi-hums.com)

Neil Seamon  
Phone: (909) 930-3600 Ext. 228  
Cell: +1-949-232-3760  
[neil.seamon@dsi-hums.com](mailto:neil.seamon@dsi-hums.com)

Document Number 26357 REV A